



## MEASURE FLOW WITHOUT LIMITS

with the Series PI Piston In-Line Variable Area Flowmeter



## **NO PIPE RUN REQUIREMENTS**

- Straight pipe runs not required before/after the meter
- Allows for installation in areas with minimal space



## NO NEED FOR POWER

Standard mechanical sensor pointer and switches



## FIELD CONFIGURABLE

- 3-wire version is equipped with a solid state relay that can be configured in the field for alarm output
- The alarm on this version is selectable between a high or low alarm (NO or NC)



**CLICK OR SCAN** 



FOR MORE INFORMATION, CONTACT US BUTLERANDLAND.COM | (800) 527-6870